NEW CLIENT LLC

In Accordance with 49 CFR Part 396 — Federal Motor Carrier Safety Regulations

ANNUAL VEHICLE INSPECTION REPORT

Report #: **12345678**

MOTOR CARRIER / OPERATOR: YOUR INSPECTION COMPANY HERE	INSPECTOR'S NAME (PRINT): INSPECTOR NAME
ADDRESS: YOUR ADRESS WILL BE HERE	CITY, STATE, ZIP: YOUR CITY
☑ This inspector meets qualification requirements — §396.19	
VIN (VEHICLE IDENTIFICATION NUMBER): VIN NUMBER HERE	UNIT / FLEET #: 1
LICENSE PLATE #	MILEAGE
INSPECTION DATE: Sep 28, 2026	VALID UNTIL: Sep 28, 2027
VEHICLE TYPE: ☑ TRUCK ☐ TRAILER	INSPECTION AGENCY / LOCATION: SHOP LOCATION

INSTRUCTIONS: ✓ OK = ITEM PASSED INSPECTION | ✗ NR = NEEDS REPAIR (ENTER REPAIR DATE) | N/A = ITEM DOES NOT APPLY TO THIS VEHICLE

Item	OK	NR	N/A	Repair Date
1. BRAKE SYSTEM				
a. Service Brakes	✓			
b. Parking Brake System	✓			
c. Brake Drums or Rotors	✓			
d. Brake Hose	✓			
e. Brake Tubing	✓			
f. Low Pressure Warning Device	✓			
g. Tractor Protection Valve	✓			
h. Air Compressor	✓			
i. Electric Brakes	✓			
j. Hydraulic Brakes	✓			
k. Vacuum Systems	✓			
2. COUPLING DEVICES				
a. Fifth Wheels	✓			
b. Pintle Hooks	✓			
c. Drawbar/Towbar Eye	✓			
d. Drawbar/Towbar Tongue	✓			
e. Safety Devices	✓			
f. Saddle-Mounts	✓			
3. EXHAUST SYSTEM				
a. Leaking — forward/below driver compartment			✓	
b. Bus exhaust — atmosphere discharge violation			✓	
c. Risk of burning wiring/fuel/combustible parts			✓	

Item	OK	NR	N/A	Repair Date
4. FUEL SYSTEM				
a. Visible Leak			✓	
b. Fuel Tank Filler Cap Missing			✓	
c. Fuel Tank Securely Attached			✓	
5. LIGHTING DEVICES				
All lighting devices & reflectors (§393) operable			✓	
6. SAFE LOADING				
a. Load/dunnage — risk of falling on roadway			✓	
b. Protection against shifting cargo			✓	
7. STEERING MECHANISM				
a. Steering Wheel Free Play			✓	
b. Steering Column			✓	
c. Front Axle Beam & Steering Components			✓	
d. Steering Gear Box			✓	
e. Pitman Arm			✓	
f. Power Steering			✓	
g. Ball and Socket Joints			✓	
h. Tie Rods and Drag Links			✓	
i. Nuts			✓	
j. Steering System			✓	
8. SUSPENSION				
a. U-bolts/Spring hangers cracked/broken/loose			✓	
b. Spring Assembly			✓	
c. Torque, Radius or Tracking Components			✓	

Item	OK	NR	N/A	Repair Date
9. FRAME				
a. Frame Members			✓	
b. Tire and Wheel Clearance			✓	
c. Adjustable Axle Assemblies (Sliding Subframes)			✓	
10. TIRES				
a. Tires on any steering axle of a power unit			✓	
b. All other tires			✓	
11. WHEELS AND RIMS				
a. Lock or Side Ring			✓	
b. Wheels and Rims			✓	
c. Fasteners			✓	
d. Welds			✓	
12. WINDSHIELD GLAZING				
Cracks/discoloration/vision reduction (§393.60)			✓	
13. WINDSHIELD WIPERS				
Inoperative/damaged wiper — power unit			✓	

List any other condition which would prevent safe operation of this vehicle:

CERTIFICATION: THIS VEHICLE HAS PASSED ALL INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 49 CFR PART 396.

INSPECTOR NAME (PRINT)	INSPECTION DATE	VALID UNTIL (12 MONTHS)
INSPECTOR NAME	Sep 28, 2026	Sep 28, 2027

© NEW CLIENT LLC · , · Annual Vehicle Inspection Report · 49 CFR §396.21 · Form TT-AVI